

RECEIVED
JAN 23 1991

DIVISION OF
OIL, GAS & MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) Aug. / '90 To (mo./yr.) Dec. / 90
2. DOGM File Number (original notice): 51027/015
3. Mine Name: Kassidy 1 and 2
4. Legal Description (Location of Lands Affected):
1/8 NE 1/4, SW 1/4, Section 14, Township T17S, Range 13W
1/8 SW 1/4, SW 1/4, Section 14, Township T17S, Range 13W
____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
5. Mineral(s) Mined: Ornamental stone
6. Name of Operator or Company: Scott Lees
7. Permanent Address: Scott Lees
5302 South 900 East Apt. 2
Murray City, Ut. 84117

8. Company Representative (or designated operator):

Name: Scott Lees

Title: N/A

Address: 5302 South 900 East Apt.2; Murray, Ut

Phone: (801) 266-5965

- ☐ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐

2. If active, how much ore or mineral was mined? Approx. 2 tons

3. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, volume of material moved, and the acreage affected.

This was the start up of the operation, so only 420 feet
of road was excavated to the start of the first terrace.
Approximately 360 cubic feet of soil and clay were stocked
piled and stabilized. Approximately 1/5 of an acre was affected.

4. Briefly describe the reclamation work performed during the past year. This description should include acreage reclaimed, methods employed, and an evaluation of the results.

Since this was a start up year only erosion control on
the road and riffraffing of a dry creek bed was done.

5. What was the total unreclaimed acreage at years end? 1/5 of an acre

6. Briefly summarize mining and reclamation planned for the upcoming year.

It is planned to start working on making the first terrace
of the qurray and making deris stock piles from overburdon
of preexisting pit dug by unknown persons.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Scott Lees

Title of Operator: N/A

Signature of Operator: 

Date: Jan. 21, 1991

jb
MNMAR-AR